

**GENERAL CONSTRUCTION (BUILDING) ANALYSIS (Continued)**

	d. Additional Comments:

6.	Floors/Framing
----	----------------

	a. Type:	Wood___	Precast Concrete___
	Cold rolled steel	Structural Concrete___	Bar Joist & Concrete Deck__
		Structural Steel & Concrete Deck	<u>X</u>

	b. General Condition of existing floor framing		
	Good___	Average___	Poor <u>X</u>
	Needs Repair___	Needs Replacement	<u>X</u>

	c. Additional Comments:
The existing floor framing(wood floor joist and ceiling joist) are generally in poor condition	

7.	Interior Partitions
----	---------------------

	a. Type:	Wood Frame___	Masonry___	Steel Studs <u>X</u>	Other___
--	----------	---------------	------------	----------------------	----------

	b. Finish:	Gypsum Wall Board <u>X</u>	Plaster___
--	------------	----------------------------	------------

	c. General Condition of interior walls		
	Good___	Average <u>X</u>	Poor___
	Needs Repair <u>X</u>	Needs Replacement	<u>X</u>