

GENERAL CONSTRUCTION (BUILDING) ANALYSIS (Continued)

2.	Exterior Walls		
	a. Type:	Wood Frame__	Masonry/Wood Frame__
	rooled cold steel	Masonry__	Other Steel frame
	b. Interior Finish:	Drywall <u>X</u>	Plaster__ Other__
	c. Siding/Veneer:	Wood__	Stone__ Aluminum__
		Vinyl__	Brick <u>X</u> Other__ Stucco
	d. Condition of the existing	Good__	Average__ Poor <u>X</u>
	walls	Needs Repair__	Needs Replacement <u>X</u>
	e. Additional Comments: The existing walls are wood frame /plaster interior wall and vinyl facade is in very poor condition		
3.	Windows		
	a. Type:	Double Hung:	Awning: Casement: <u>X</u>
	aluminum	Sliding:	Other:
		Storm Windows: Yes__ No__ N/A	
		Screens: Yes <u>X</u> No__	
	b. Material:	Wood:	Steel: Vinyl:
		Aluminum: <u>X</u>	Clad:
	c. Glazing:	Single:	Double: <u>X</u> Insulating: <u>X</u>
	d. Condition of the existing	Good:	Average: Poor: <u>X</u>
	windows	Needs Minimal Repair:	Rec. Replacement No.:
	e. Additional Comments: The existing windows are generally in poor condition.		