

GENERAL CONSTRUCTION (BUILDING) ANALYSIS (Continued)

d. Additional Comments:

8. Ceilings

a. Finishes:

Metal___ Gypsum Wall Board X Plaster___

Acoustic Tile___ Other_____

b. General Condition of exiting ceiling

Good___ Average_____ Poor X

Needs Repair_____ Needs Replacement X

c. Additional Comments:

The existing ceiling from plaster is generally in fair condition

9. Flooring Finishes

a. Finishes:

Hard Wood X Carpet___ Ceramic X

Parquet___ VCT___ Quarry Tile___

b. General Condition of existing flooring finishes

Good___ Average_____ Poor X

Needs Repair___ Needs Replacement X