

GENERAL CONSTRUCTION (BUILDING) ANALYSIS (Continued)

c. Additional Comments:			
The existing floor finishes condition are very poor			
10.	Kitchen Cabinetry		
a. Type: Proposed formica kitchen cabinetry			
b. General Condition of existing kitchen			
		Good___	Average___
		Needs Repair <u>X</u>	Needs Replacement___