

**ELECTRICAL ANALYSIS (Continued)**

d.Existing Condition:			
Good	<input type="checkbox"/>	Average	<input type="checkbox"/>
Poor	<input checked="" type="checkbox"/>		
Needs Repair		<input type="checkbox"/>	Needs Replacement
		<input checked="" type="checkbox"/>	
e. Additional Comments:			
8.	Elevators (Elevators)		
a. Elevator(s)	<input checked="" type="checkbox"/>	YES	<input type="checkbox"/>
		<input type="checkbox"/>	NO
Operational Service Contract:			
		<input checked="" type="checkbox"/>	YES
		<input type="checkbox"/>	NO
b. Inspection/tests reports available:	N/A		
		<input type="checkbox"/>	YES
		<input type="checkbox"/>	NO
Addition Comments:			
Proposed a lift instead a elevator which will reach basement and 1st floor.			